



NOTES:

1. EACH VOLTAGE INDICATE BETWEEN POINT © AND THE LINE.
2. VALUE OF * MARKED PARTS SELECTED IN MANUFACTURING.
3. THERE ARE NO PRE-SET CONTROL ASSY, AR-3 AND MARKED PARTS IN THE RC5A-2.
4. THERE ARE NO * MARKED PARTS IN THE RC5-3.
5. C6 THRU C9 ADDED IN SOME UNIT DURING FINAL TESTS.

Figure 6-3. Indicator Control RC5A-3, RC5A-2, RC5-3, Schematic Diagram.